



JoinTec

Flügge

Paderborn, den 25. Mai 2010


Index

Leaking pipe joints

- ▶ Possible failure causes
 - ▶ **Shrinking of the adhesive**
 - ▶ **Water pressure / load case**

Jointec

Test procedure to open the joints



Appearance of fracture of pipe bonds with defects



Appearance of fracture of pipe bonds without failure



- ▶ **No adhesion between adhesive and pipe surface**
- ▶ **Water damage on the surface**
- ▶ **Mostly no adhesion on the pipe side but on the sleeve side**



Possible explanations for the phenomena of no adhesion at the pipeline sided bond line are:

- ▶ Adhesive shrinkage
- ▶ Handling issues through rotation
- ▶ Possible crack at the bond line

Unfortunately the tests do not show some shrinkage either a crack, probably because of the adhesive quantity. New tests are coming with some other preparation.



Crack check




Bild 1
B_249532
Übersicht

Makro




Bild 2
B_249994
Bereich 1
Keine Poren oder Risse in der Klebschicht erkennbar.

Compo 25: 1




Bild 5
B_249996
Bereich 3
Keine Poren oder Risse in der Klebschicht erkennbar.

Compo 25: 1






Bild 4
B_249997
Detail 2
Darstellung der Klebschicht

100: 1

Failure caused by pressure: Test setup



Failure caused by pressure



test 1: leak at 180 bar




test 2: no leak at 300 bar


Results:

- Damages forced by water are not the same compared to damages at pipes
- Pressure higher as 300 bar was possible
- No „scalpel effect“

Jointec

Not cured areas





mixture after 1 day



mixture after 6 days

liquid Isocyanides



mixture after 2 weeks

liquid Polyol

Results:

- After 1 day: building of a hard surface
- After 6 day: liquid isocyanides is leaking out of the surface
- After 2 weeks:
 - Removing of the glass
 - Polyol next to the glass still liquid
 - Liquid isocyanides is crystalline